

## **Suzanne Steab - February 2011 Inspection Reports**

K

From:

Karl Houskeeper

To:

JohnGefferth@consolenergy.com; PeterBehling@consolenergy.com; SteveBe...

Date:

3/3/2011 3:05 PM

Subject:

February 2011 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments:

Emery Deep February 2011.pdf; Hidden Valley February 2011.pdf

Attached are the February 2011 inspection reports for Emery Deep and Hidden Valley.

Thanks,

Karl



GREG BELL
Lieutenant Governor

# State of Utah

**DEPARTMENT OF NATURAL RESOURCES** 

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Peter Behling				
OGM	Karl Houskeeper				

## **Inspection Report**

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, February 22, 2011
Start Date/Time:	2/22/2011 9:00:00 AM
End Date/Time:	2/22/2011 12:30:00 PM
Last Inspection:	Wednesday, January 19, 2011

Inspector: <u>Karl Houskeeper</u>, Weather: <u>Clear, Temp. 32 Deg. F.</u> InspectionID Report Number: <u>2655</u>

Accepted by: jhelfric 3/3/2011

Permitee: CONSOLIDATION COAL CO
Operator: CONSOLIDATION COAL CO

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cur	rent	Acreages

442.50	<b>Total Permitted</b>
248.50	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

Mineral	Ownership
---------	-----------

✓ Federal

State

☐ County
✓ Fee

✓ Fee Other **Types of Operations** 

✓ Underground

Surface
Loadout
Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Douskeper

Date

Tuesday, February R011

OIL, GAS & MINING

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 22, 2011

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
  2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
  4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	1 1			
2.	Signs and Markers	¥.		Y	
3.	Topsoil	D			
4.a	Hydrologic Balance: Diversions			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
<b>4.</b> b	Hydrologic Balance: Sediment Ponds and Impoundments	1 (			: ]
4.c	Hydrologic Balance: Other Sediment Control Measures	¥		V	
4.d	Hydrologic Balance: Water Monitoring	474755 			
4.e	Hydrologic Balance: Effluent Limitations		1.00	(1)	
5.	Explosives			1	
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	)	ghanning Company	**************************************	
8.	Noncoal Waste	Trens			13
9.	Protection of Fish, Wildlife and Related Environmental Issues		: 27		
10.	Slides and Other Damage			: )	
11.	Contemporaneous Reclamation	[]			
12.	Backfilling And Grading			<u> </u>	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations			L.)	
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls	[]			
17.	Other Transportation Facilities				F
18.	Support Facilities, Utility Installations				
19.	AVS Check		,		
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	Ÿ.		V	:

Permit Number: C0150015
Inspection Type: PARTIAL

Inspection Date: Tuesday, February 22, 2011

Page 3 of 3

### 2. Signs and Markers

The mine identification signs were observed in place at the Main Facility and 4th East Portal Area. Both signs are situated so that they are at the contact point of public access into the permit area. Both signs contains the required information.

#### 4.c Hydrologic Balance: Other Sediment Control Measures

Silt fence located in one of the storage areas at the 4th East Portal area needs to be replaced. The site has been monitored for several months, but recent wind events has made the silt fence non-functional. The area had already been identified as needing maintenance by company personnel and is scheduled to be replaced this week.

#### 22. Other

Portions of wind fence identified in previous inspections as needing maintenance has been replaced by new material since the prior inspection.